
T-EPE-0009-E Assembly of Center Bearing

This process demonstrates the Assembly of Center Bearing.

Redigido por: Luis Ferreira





INTRODUÇÃO

Technical Information:

- **No:** T-EPE-0009-01-11 **Replaces No:** T-EPE-0009-00-11
- Distribution: EPE, VV, VTK, EPT


Passo 1 — Assembly






- After assembling, the center bearing must be free of prestress
- The static axial displacement must not exceed s = ±3mm

Passo 2





- The maximum resulting angular displacement must not exceed βres = ±3°