




Perform zero calibration

Written By: Tanya Taylor



INTRODUCTION

If you have a Series 500 or Series 300 handheld monitor, you can zero calibrate the Type 1 sensor heads you use with your Series 900 fixed monitor. The only exceptions are ammonia and perchlorethylene. For these Type 1 sensors, you must return them for factory calibration or buy replacements.


To perform a zero calibration in the field using a Series 500 or Series 300 handheld monitor, you also need Aeroqual's calibration accessory (AS R42) with 10ml syringe, Tygon tubing, a gas regulator and gas cylinders.

Step 1 — Perform zero calibration



- [Click here to set up the calibration accessory.](#)

Step 2



- [Click here to perform the zero calibration.](#)

For further support, contact [Technical Support](#).