
Mummy

Use stiff felt, craft foam or cardstock to make this Mummy with two LEDs.

Written By: Amanda Etim



INTRODUCTION

Use stiff felt, craft foam or cardstock to make this Mummy with two LEDs.

You can make this project (and many more!) with our Wearable Circuits Kit or our Paper Circuits Kit.

TOOLS:


- Scissors (1)
- Glue (1)
- Safety Pin (1)

PARTS:


- Wearable Circuits Kit (1)
- Felt (1)

© 2025

Step 1 — Print and Cut Template







- **Print out the template** on heavy cardstock.

ⓘ We have included a full color template as well as a black and white template. Print the one that works better for your printing needs.

- **Cut** out each part of the template.

Step 2 — Trace and Cut Parts






- Use the template to **trace the parts** onto stiff felt, craft foam, or cardstock.
- **Cut** out the parts.

ⓘ You will need to cut out multiple strips of white for your Mummy. These strips can vary in width depending on the look you want to achieve.

Step 3 — Assemble the Mummy






- Use glue to **assemble** the Mummy with the strips in any arrangement you prefer, leaving a small area for the eyes. The strips should go passed the edge of the oval. We will trim and glue the edges in the next step.

ⓘ Regular Elmers glue and Tacky glue both work well, but you will need to give the Mummy time to dry overnight before adding the circuit. Hot glue also works well and dries fast so you can build the circuit right away.

Step 4 — Trim and Wrap Strips


- If your strips hang over the edge of the oval by more than an inch you should **trim the excess material** back so you only have about an inch hanging over the sides of the oval.
- Flip the Mummy over and **wrap each strip** around to the back. Secure each strip in place with glue.

Step 5 — Poke Holes for LED Legs



- Use a safety pin or a push pin to **poke four holes (two for each LED)** through the felt for the LED legs to go through.

Step 6 — Add the LEDs



- **Add the LEDs** by pushing the legs through the holes.

⚠ Note! Make sure the longer **Positive (+)** legs are in the middle of the project when you put the legs through the holes.

© 2025


Step 7 — Bend LED Legs





- Bend the longer (**Positive**) LEDs legs toward the middle. They will overlap and that is ok.
- Bend the shorter (**Negative**) LED legs down towards the bottom.

Step 8 — Add Maker Tape






- Place a piece of **Maker Tape UNDERNEATH** each LED leg.
- Place another piece of **Maker Tape OVER THE TOP** of the LED legs so the LED legs have Maker Tape under and on top of them.


ⓘ Two layers of Maker Tape create a "tape sandwich" with the LED legs in the middle. Since the felt isn't as flat as paper this will help create a better electrical connection.


Step 9 — Add More Maker Tape




- Use a piece of **Maker Tape to connect** the two outside (**Negative**) pathways.

Step 10 — Add Tape Loop and Battery







- Make a **loop of tape** (sticky side out) using a short piece of Maker Tape, and stick it atop the middle of the tape pathway connecting the two longer (**Negative**) pathways.
- Once your **Tape Loop** is in place you can add the **Battery** to it.


☒ Make sure the **Positive** side of the Battery is facing upwards, with the **Negative** side stuck down to the tape.

Step 11 — Add Maker Tape



- **Add Maker Tape** to connect the top (**Positive**) side of the battery to the **Positive** LED legs path above.

Step 12 — Mummy Assembled



- Your Halloween Mummy craft is assembled and ready to show off to other!