Bucknell UNIVERSITY

Clearing jobs from the Thunder Laser

Sometimes there are too many stored files on the Thunder Laser which can cause problems with new jobs. This guide shows you how to delete stored files.

Written By: Matt P. Lamparter

Step 1 — Enter file menu



- Turn on the Thunder Laser main switch. Do not turn on the laser switch.
- Once the machine finishes booting up, press the **File** button to enter the file menu.

Step 2 — Select and delete file(s)





- Use the **up and down arrow keys** to navigate to the file you would like to delete. With the file highlighted, press the **right arrow key** once to select the file. Press the **down arrow key** to select **Delete**.
- Hit the **Enter** button to delete the file. Depending on the size of the file this may take several seconds. When the deletion is complete the screen will display **Delete Successful**. Press **Enter** to continue.
- Be sure to turn off the laser cutter when you are done.