

# G2 Measure Track Height

Written By: Todd Lucas



## Step 1 — Measure Track Height




- Lay one of the Vertical Track Assemblies on your work surface.
- ⚠ Measure the Length of the Aluminum Track only.
- Add 1/4" to the Track dimension.
- This is the Height dimension needed to mark the location of the Bottom edge of the Header Mounting Brackets.