

Install G1 Standard Projection Mount Brackets - Roll Header

Written By: Trent Borgardt




Step 1 — Bracket Orientation Guide



- ⓘ Orient the slotted end of the Header Mounting Projection Bracket against the Mounting Surface.
- ⓘ Orient the flange outward.
- Align the Bottom surface of the Header Mounting Bracket with the Horizontal line on the Mounting Surface.
- Align the Outer edge of the Header Mounting Bracket with the Vertical line on the Mounting Surface.
- Trace the slotted mounting slots onto the Mounting Surface.

Step 2 — Securing Bracket to Mounting Surface



- Loosely fasten Bracket to the Mounting Surface with appropriate hardware.
- Plumb the Bracket.
- Tighten Hardware securely.
- Repeat for the other Header Mounting Bracket.

© 2026