

Shutting Down the Smith Little Torch



Step 1 — Turn off the torch



- Turn the oxygen (green) and fuel (red) torch knobs clockwise until closed.

Step 2 — Turn off the oxygen tank



- Turn the oxygen tank valve clockwise until completely closed.

Step 3 — Turn off the propane tank



- Turn the propane tank valve until completely closed.
- Non-Regulated valves turn counter-clockwise
- Regulated valves turn clockwise

Step 4 — Remove Torch tip



- Remove torch tip.
- Caution: Tip may be hot!

Step 5 — Draining hoses



- Open Green oxygen torch knob 1/2 turn until oxygen flow stops and both regulator gauges read zero.
 - The left pressure gauge will go up during the process, this is normal.
- Open red propane torch knob 1/2 turn until flow stops.
- Turn both torch knobs clockwise until closed
- Secure torch hoses.
- turn the regulators until you do not feel spring pressure. if the screw comes out, yo went too far. Screw it back in one to two full turns.