
RX - How to Use EASY Analyzer to Troubleshoot Touchscreen Issues

Written By: Dozuki System





This document was generated on 2022-01-05 06:10:46 PM (MST).


INTRODUCTION

© 2022

Step 1 — Using Easy Analyzer (Multi Touch Paint Tool)









- Click on the Windows logo on a USB keyboard or the touchscreen keyboard on the pendant. Then select the Computer tab.
- Select the Desktop icon, which will bring up files and folders within the desktop.
- Select the easyAnalyzer program and open.




Step 2 — Using Easy Analyzer (Multi Touch Paint Tool) Cont.





- Select the Multi Touch Paint Tool.
- Use 3 fingers to swipe across screen as shown in image 2.

Step 3 — Using Easy Analyzer (Touchscreen Intensity Graph)

- Select "PLAY" icon on screen to begin touchscreen intensity test.
- This will then open up the screen intensity graph as shown in image 2.
- Press on touchscreen to see intensity "spike" on screen as shown in image 3.

When finished using the intensity graph, you must use a USB keyboard with a mouse pad or a USB mouse to select the "STOP" button at the top of the screen.