
How to Export a Screenshot on the SINUMERIK Control

Take a screenshot of the control screen and copy it to a USB stick.

Written By: Ashley Nilges



This document was generated on 2026-11-16 04:20:55 AM (MST).

INTRODUCTION




← TRAKsi Tech Support: start here

A screenshot shows TRAK Tech Support exactly what you are seeing. No password needed.

Other TRAKsi Tech Support guides: Software Version · Alarm Log · Archive · Diagnostic File (DiDac) · Button-Press Log · ATC Magazine


© 2026


Step 1 — Take the Screenshot

- With the screen you want on display, press the camera icon in the right column of softkeys.
- Go to **[Setup]** (wrench icon on the left) → **[System data]** (bottom row of softkeys).
- In the folder list, open **Logs**, then **Screen shots**.
  - Screenshots are numbered. The highest number is the newest.

Step 2 — Copy the Screenshot to USB





- Plug a USB stick into the USB port on the right side of the pendant.
- Select the screenshot, then press **[Mark]** and **[Copy]** in the right column of softkeys.
- Select the USB stick in the folder list and press **[Paste]**. The screenshot is now on the USB stick.
- Send it to TRAK with the other items on the TRAKsi Tech Support page.

This document was generated on 2026-11-16 04:20:55 AM (MST).